

Inspection Photos
Location Name: Carlson 15-D Pad
Location ID: 331351



Colorado Oil and Gas Conservation Commission
40.40321, -104.64059, 4549.3ft, 273°
06/11/2020 07:28:56 AM



Colorado Oil and Gas Conservation Commission
40.40325, -104.64059, 4551.3ft, 309°
06/11/2020 07:29:00 AM

Photo #1 Tank Battery/ Lact

Photo #2 Maintenance Tank

Inspection Photos
Location Name: Carlson 15-D Pad
Location ID: 331351



Photo #3 Meter Runs



Photo #4 Well & Signs

Inspection Photos
Location Name: Carlson 15-D Pad
Location ID: 331351



Photo #5 Separators



Photo #6 ECD's

Inspection Photos
Location Name: Carlson 15-D Pad
Location ID: 331351



Photo #7 ECD



Photo #8 Lact and Pig Station

Inspection Photos
Location Name: Carlson 15-D Pad
Location ID: 331351



Photo #9 Condensate Pit



Photo #10 Condensate Pit

Inspection Photos
Location Name: Carlson 15-D Pad
Location ID: 331351



Photo #11 Unused Secondary Tub

Photo #12 Unused Secondary Tub

Inspection Photos
Location Name: Carlson 15-D Pad
Location ID: 331351



Photo #13 Unused Jersey Barriers



Photo #14 Small back ecd flame rack