

Inspection Photos
Location Name: Bighole-Fed Land Bank
Location ID: 312931



Photo 1. Overview of location taken facing southwest.



Photo 2. Annual weeds on location.



Inspection Photos
Location Name: Bighole-Fed Land Bank
Location ID: 312931



Photo 3. Incomplete or missing tank labels.



Photo 4. Incomplete or missing tank labels.



Inspection Photos
Location Name: Bighole-Fed Land Bank
Location ID: 312931



Photo 5. Risers not labeled or LOTO.



Photo 6. Hissing at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bighole-Fed Land Bank
Location ID: 312931



Photo 7. Erosion gully leaving location. Photo taken from access road looking towards location.



Photo 8. Erosion gully origin on east side of location. Containers without secondary containment.



Inspection Photos
Location Name: Bighole-Fed Land Bank
Location ID: 312931



Photo 9. Erosion gully leaving location. Photo standing on location perimeter looking towards access road.



Photo 10. Erosion leaving location. Photo standing on location perimeter looking towards access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources