



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Well bore.

Husky Oil Co 5

API: 05-103-40358

Inspection: 700402319



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Inside hole with bottom visible in picture.

Husky Oil Co 5

API: 05-103-40358

Inspection: 700402319



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well covered with boards after inspection completed.

Husky Oil Co 5

API: 05-103-40358

Inspection: 700402319