

# Final Reclamation Inspection

July 13, 2020

Operator: FRITZLER RESOURCES INC - #31257

Location ID: 470894

Inspection Document #: 697501760

Weld County, CO

NESW Section 17 T7N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Law 1 Tank Battery  
Location ID: 470894



**Photo 1.** Photo taken from the southern tank battery, facing North. Photo illustrates the Operator has failed to perform final reclamation activities at the tank battery.

Note: it appears the surface owner is using the tank battery area for farming operations.

Inspection Photos  
Location Name: Law 1 Tank Battery  
Location ID: 470894



**Photo 2.** Photo taken from the northern tank battery, facing North.  
Photo illustrates a loaded point that is likely used by the surface owner.