

# Inspection Photos

API: 017-07255

Operator: KUENZLER & FLORA RESERVE COMPANY

Inspection Date: 7/13/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 017-07255 | Date: 7/13/2020

## Inspection Photos



**Photo 1.** Facing north at the beginning of the access road.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07255 | Date: 7/13/2020

## Inspection Photos



**Photo 2.** Facing north toward the location. Sign is laying on the ground at the location.



**Photo 3.** The electric fence around the location is in disrepair.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07255 | Date: 7/13/2020



## Inspection Photos



**Photo 4.** Facing north toward the location. The soils are bare of vegetation and will need to be reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07255 | Date: 7/13/2020

## Inspection Photos



**Photo 5.** The soils are bare of vegetation and will need to be reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07255 | Date: 7/13/2020



## Inspection Photos



**Photo 6.** The well remains at center of the location and is currently TA.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07255 | Date: 7/13/2020



## Inspection Photos



**Photo 7.** Facing southeast at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07255 | Date: 7/13/2020

## Inspection Photos



**Photo 8.** Facing west toward the surrounding pasture.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07255 | Date: 7/13/2020