

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

Photo 1. Location.

Stanger 6 API: 05-103-07362
Inspection: 700402581



COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

Photo 2. Stained soil.

Stanger 6 API: 05-103-07362
Inspection: 700402581



COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

Photo 3. Containers with fluid at pump jack.

Stanger 6 API: 05-103-07362
Inspection: 700402581



COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

Photo 4. Stained pile of dirt.

Stanger 6 API: 05-103-07362
Inspection: 700402581