

BP L48 San Juan



V2 Compliance Follow Up Form

18148399762

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200716-18148399762

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Jul 16, 2020 7:19:16 AM MDT

91 S Skylane Dr, Durango, CO 81303, USA

Jul 16, 2020 7:19:07 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jun 19, 2020

Well Name

LECHNER, OPAL GAS UNIT A 1

API Number

50670733600

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Other

Photo of first corrective action completed



**Completed work description Corrective
Action 1**

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

pad clean of vegetation

Photo of third corrective action completed



**Completed work description of corrective
action 3**

reclamation area clean of noxious weeds

Photo of fourth corrective action completed

**Completed work description**

reclamation area clean of noxious weeds

Completed work description of corrective action 4

site was treated on 6/19/20 and a follow up treatment was done on 7/9/20

Completed work description

treated noxious weeds on pad and in reclamation area

Summary of all work completed

previous treatment dates 6/28/16, 6/28/17, 6/20/18, 5/8/19, 6/19/20, 7/9/20