



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Ant Hill Unit 18-23

API: 05-103-10902

Inspection: 700402950



40.145, -108.20363, 6251 1ft, 49°
08/17/2020 03:03:53 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Ant Hill Unit 18-23

API: 05-103-10902

Inspection: 700402950



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Meter building.

Ant Hill Unit 18-23

API: 05-103-10902

Inspection: 700402950



40.14479, -108.20319, 6247.8ft, 21°
08/17/2020 03:07:03 PM



40.14486, -108.20324, 6253.4ft, 44°
08/17/2020 03:05:11 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tanks.

Ant Hill Unit 18-23

API: 05-103-10902

Inspection: 700402950