

Inspection Photos
Operator Name: RANCHO TRES
Facility ID: 322300
BERT EATON (OWP) 1



Location Photo



Access trail in good condition,

Inspection Photos
Operator Name: RANCHO TRES
Facility ID: 322300
BERT EATON (OWP) 1



Location Photo, wellhead is protected inside
small shed

Inspection Photos
Operator Name: RANCHO TRES
Facility ID: 322300
BERT EATON (OWP) 1




Wellhead, gauge on left shows 180psi, in my inspection in 04/30/2018 I noted 30psi on gauge



Wellhead is open to atmosphere

Inspection Photos
Operator Name: RANCHO TRES
Facility ID: 322300
BERT EATON (OWP) 1



Yellow 1" flowline exiting cellar