FORM INSP

Rev X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109





Inspection Date: 08/27/2020
Submitted Date: 08/27/2020

Document Number: <u>700701431</u>

## FIELD INSPECTION FORM

**Status Summary:** Loc ID Inspector Name: On-Site Inspection THIS IS A FOLLOW UP INSPECTION 335529 Ramsey, Scott 2A Doc Num: FOLLOW UP INSPECTION REQUIRED **Operator Information:** NO FOLLOW UP INSPECTION REQUIRED OGCC Operator Number: 96850 Findings: Name of Operator: TEP ROCKY MOUNTAIN LLC Number of Comments 23 Address: PO BOX 370 **Number of Corrective Actions** City: **PARACHUTE** State: CO Zip: 81635 Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE **Contact Information:** 

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@t erraep.com	

Inspected I	Facilities:						
Facility ID	Туре	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297017	WELL	PR	01/26/2009	GW	045-16264	KOKOPELLI FED 18-213D	PR
297018	WELL	PR	01/26/2009	GW	045-16265	KOKOPELLI FED 18-313D	PR
297019	WELL	PR	01/26/2009	GW	045-16266	KOKOPELLI FED 18-215D	PR
297020	WELL	PR	07/10/2014	GW	045-16267	KOKOPELLI FED 18-315D	PR
417052	WELL	PR	09/06/2012	GW	045-19446	Federal KP 544-18	PR
417053	WELL	SI	05/01/2020	GW	045-19447	Federal KP 344-18	SI
417057	WELL	PR	07/03/2013	GW	045-19448	Federal KP 414-18	PR
417059	WELL	PR	12/11/2018	OG	045-19449	Federal KP 523-18	PR
422763	WELL	PR	10/17/2012	GW	045-20625	Federal KP 14-18	PR
422769	WELL	PR	10/17/2012	GW	045-20626	Federal KP 24-18	PR
422774	WELL	PR	10/17/2012	GW	045-20627	Federal KP 34-18	PR
422783	WELL	PR	10/17/2012	GW	045-20628	Federal KP 533-18	PR
422785	WELL	PR	01/02/2013	GW	045-20629	Federal KP 514-18	PR
422788	WELL	PR	10/17/2012	GW	045-20630	Federal KP 433-18	PR
422792	WELL	PR	11/28/2012	GW	045-20631	Federal KP 534-18	PR
422795	WELL	PR	10/17/2012	GW	045-20632	Federal KP 44-18	PR
422796	WELL	PR	01/18/2013	GW	045-20633	Federal KP 524-18	PR
422799	WELL	PR	12/20/2012	GW	045-20634	Federal KP 444-18	PR
422801	WELL	PR	10/17/2012	GW	045-20635	Federal KP 314-18	PR

## **General Comment:**

Inspector Name: Ramsey, Scott
COGCC Inspection Report Summary On Thursday 8/27/20 at approximately 1230, I, Inspector Scott Ramsey, conducted a routine inspection at TEP KP 34-18, at Location # 335529 in Garfield county Colorado. While there, I observed normal production operations. All meters have been calibrated on location within the past year. This is a summary of inspection report.
While there, I observed normal production operations. All meters have been calibrated on location within the past year.  This is a summary of inspection report.

		<u> </u>	<u>Location</u>				
Lease Road:							
Туре	Access						
comment:							
Corrective ActionL				Date:			
Overall Good: 🔀							
Signs/Marker:							
Туре	WELLHEAD						
Comment:							
Corrective Action:				Date:			
Туре	BATTERY						
Comment:							
Corrective Action:				Date:			
Туре	CONTAINERS						
Comment:							
Corrective Action:		Date:					
Туре	TANK LABELS/PLACARE						
Comment:							
Corrective Action:		Date:					
Emergency Contact N	Number:						
Comment:	911						
Corrective Action:				Date:			
Good Housekeeping	<u>1:</u>						
Туре	DEBRIS						
Comment:							
Corrective Action:							
Overall Good: 🔀							
Spills:							
Туре	Area	Volume					
In Containment: N	lo		1				
Comment:							
Multilple Spills a	and Releases?						
Fencing/:							
Туре	SEPARATOR						
Comment:							
Corrective Action:				Date:			
Type	TANK BATTERY						
Comment:							
Corrective Action:				Date:			

Inspector Name: Ramsey, Scott Type WELLHEAD Comment: Corrective Action: Date: **Equipment:** corrective date Type: Plunger Lift # 19 Comment: Corrective Action: Date: Type: Ancillary equipment #2 Comment: chemical tanks at well heads Corrective Action: Date: Type: Gas Meter Run # 19 Comment: All meters calibrated on location within a year. Corrective Action: Date: Type: Bird Protectors # 18 Comment: Corrective Action: Date: Type: Horizontal Heated Separator # 20 Comment: Corrective Action: Date: Type: Horizontal Heater Treater # 1 Comment: Corrective Action: Date: Venting: Yes/No NO Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

				Inspected	d Facilities				
acility ID:	297017	Туре:	WELL	API Number:	045-16264	Status:	PR	Insp. Status:	PR
				Produc	ing Well				
С	omment: pro	ducing							
Correctiv	e Action:							Date:	
acility ID: _	297018	Type: _	WELL	API Number:	045-16265	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
С	omment: pro	ducing							
Correctiv	e Action:							Date:	
acility ID: _	297019	Type: _	WELL	API Number:	045-16266	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
С	omment: pro	ducing							
Correctiv	e Action:							Date:	
acility ID: _	297020	Type: _	WELL	API Number:	045-16267	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
С	omment: pro	ducing							
Correctiv	e Action:							Date:	
acility ID:	417052	Type: _	WELL	API Number:	045-19446	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
С	omment: pro	ducing							
Correctiv	e Action:							Date:	
acility ID:	417053	Type: _	WELL	API Number:	045-19447	Status: _	SI	Insp. Status:	SI
				Idle V	Vell				
Purpos	se: 💢 Shut I	n 🔽	Temporarily		Reminder:				
-	comment: las								
	e Action:	. p. oddood						Date:	
acility ID:	417057	Type: _	WELL	API Number:	045-19448	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
С	omment: pro	ducing							
Correctiv	e Action:							Date:	
			WELL	API Number:	045-19449	Status:	PR	Insp. Status:	PR

inspector Na				Produc	ing Well				
Co	omment: pro	ducing							
Corrective	e Action:	<u> </u>						Date:	
Facility ID:	422763	Type:	WELL	API Number:	045-20625	Status:	PR	Insp. Status:	PR
				Produc	ing Well				
Co	omment: pro	ducing							
Corrective	e Action:							Date:	
Facility ID: _	422769	Type: _	WELL	API Number:	045-20626	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
Co	omment: pro	ducing							
Corrective	e Action:							Date:	
Facility ID: _	422774		WELL	API Number:	045-20627	Status: _	PR	Insp. Status:	PR
				<u>Produc</u>	ing Well				
Co	omment: pro	ducing							
Corrective	e Action:							Date:	
	·								
Facility ID: _	422783		WELL	API Number:	045-20628	Status: _	PR	Insp. Status:	PR
				<u>Produc</u>	ing Well				
Co	omment: pro	ducing							
Corrective	e Action:							Date:	
Facility ID: _	422785	Type: _	WELL	API Number:	045-20629	Status: _	PR	Insp. Status:	PR
				Produc	ing Well			_	
Co	omment: pro	ducing							
Corrective	e Action:							Date:	
Facility ID:	422788		WELL	API Number:	045-20630	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
	omment: pro	ducing							
Corrective	e Action:							Date:	
Facility ID: _	422792		WELL	API Number:	045-20631	Status: _	PR	Insp. Status:	PR
				<u>Produc</u>	ing Well				
	omment: pro	ducing							
Corrective	e Action:							Date:	
Facility ID: _	422795		WELL	API Number:	045-20632	Status: _	PR	Insp. Status:	PR

Inspector Name: F	Ramse	y, Scott							
	_			Produc	ing Well				
Comme	ent: pro	oducing							
Corrective Acti	on:							Date:	
Facility ID: 422	796	Type: _	WELL	API Number:	045-20633	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
Comme	ent: pro	oducing							
Corrective Acti	on:							Date:	
Facility ID: 422	799	Type:	WELL	API Number:	045-20634	Status:	PR	Insp. Status:	PR
				Produc	ing Well			_	
Comme	ent: pro	oducing		Produc	ing Well				
Comme Corrective Acti		oducing		Produc	ing Well			Date:	
		oducing		Produc	ing Well			Date:	
Corrective Acti		oducing  Type:	WELL	Produc	ing Well 045-20635	Status:	PR	Date:	PR
Corrective Acti	on:		WELL	API Number:	-	Status:	PR		PR
Corrective Acti	801		WELL	API Number:	045-20635	Status: _	PR		PR
Corrective Acti	801 ent: pro	Type: _	WELL	API Number:	045-20635	Status:	PR		PR
Corrective Acti Facility ID: 422 Comme	801 ent: pro	Type: _	WELL	API Number:	045-20635	Status: _	PR	Insp. Status:	PR
Corrective Acti Facility ID: 422 Comme	801 ent: pro	Type: _	WELL	API Number:	045-20635	Status: _	PR	Insp. Status:	PR

msey, Scott						
	<u> </u>	Reclamat	tion - Storm	Water - Pit		
BMP Maintenance	Lease Road I BMPs	Erosion	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
	Culverts					
	Gravel					
	Ditches					
	CATION OF P	ΊΤ				Date:
ents						
GCC Images (	https://cogcc	:.state.co.u	<u>ıs/weblink/</u> ) an	d search by doc	ument number:	
escription		URL				
hoto log		http://ogccv	weblink.state.co	.us/DownloadDocu	umentPDF.aspx?[	DocumentId=5234133
: =	BMP Maintenance	BMP Maintenance  Culverts  Gravel Ditches  BURFACE INDICATION OF P	Reclamate  BMP	Reclamation - Storm  BMP	Reclamation - Storm Water - Pit    BMP	Reclamation - Storm Water - Pit    BMP