

Inspection Photos

API: 071-09084

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/2/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09084 | Date: 9/2/2020

Inspection Photos



Photo 1. Facing southwest along the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09084 | Date: 9/2/2020

Inspection Photos



Photo 2. Facing southwest along the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09084 | Date: 9/2/2020

Inspection Photos



Photo 3. Facing northwest toward the location. Gravel remains around the location and there is a culvert that has not been removed. Location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09084 | Date: 9/2/2020

Inspection Photos



Photo 4. Facing northwest toward the location. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09084 | Date: 9/2/2020

Inspection Photos



Photo 5. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09084 | Date: 9/2/2020