

# *Inspection Photos*

*Loc#334834*

*Operator: Caerus*

*Inspection Number: 692402497*

*Inspection Date: 9/11/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

Overview of Location. Signs are up.

September 11, 2020