

Inspection Photos

API: 071-06399

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/11/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 9/11/2020

Inspection Photos



Photo 1. Facing southeast at the beginning of the access road. There is noxious weeds in the area circled.



Photo 2. There is Canada thistle shown in area of previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 9/11/2020

Inspection Photos



Photo 3. Facing southeast along the access road. There are areas along the beginning portion of the road that could use additional hand seeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 9/11/2020

Inspection Photos



Photo 4. Facing southeast along the reclaimed access road.



Photo 5. There are noxious weeds in the rock rip/rap drainage shown in previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 9/11/2020

Inspection Photos



Photo 6. Facing southeast along the reclaimed road. The vegetation is establishing well along this portion of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 9/11/2020

Inspection Photos



Photo 7. Facing south along the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 9/11/2020

Inspection Photos



Photo 8. Facing south near the location. This area could use additional hand seeding to stabilize the slope with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 9/11/2020

Inspection Photos



Photo 9. Facing south toward the location. Vegetation is establishing well at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 9/11/2020

Inspection Photos



Photo 10. Facing southeast toward the reclaimed access road across the canyon.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 9/11/2020