

Inspection Photos
Location Name: SEGL Pad
Location ID: 336655




Photo 1: Wellhead Sign



Photo 2: Stained soil



Inspection Photos
Location Name: SEGL Pad
Location ID: 336655




Photo 3: Wellhead Sign



Photo 4: Battery removed

Inspection Photos
Location Name: SEGL Pad
Location ID: 336655



Photo 5: Unused equipment outside of fencing



Photo 6: Stained soil