

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2020

Submitted Date:

09/30/2020

Document Number:

691201366

## FIELD INSPECTION FORM

 Loc ID \_\_\_\_\_ Inspector Name: Graber, Candice (Nikki) On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

 Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	
Canfield, Chris		chris.canfield@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477603	SPILL OR RELEASE	AC	08/10/2020		-	Peltier #2 Flowline	EI

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Inspected Facilities**

Facility ID: 477603 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Inspection of Spill 477603 progress. Per the Supplemental Form 19 submitted on 8/6/2020 operator has not conducted delineation of the horizontal or vertical impacts to soils and extent of impact is not known. Inspection did not find evidence of any additional excavation or soil borings being performed at this site.

Corrective Action: Operator shall provide documentation of completed remedial actions within 45 days of the spill date. Supporting documentation shall include confirmation soil samples to document removal of impacts from soil in the release area and a site diagram that illustrates the release extent and location of confirmation soil samples. Date: 08/31/2020

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201368	Release Location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5259545">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5259545</a>