

Inspection Photos

API#081-07357

Operator: Foundation Energy

Insp#: 692402550

Insp Date: 9/23/2020





Photo#1:

Overview of Location to Southeast. PA Marker indicated by arrow.

September 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Foundation Energy PA Arkansas Post API#081-07357



Photo#2:
Scotch thistle in spots on what was Pad area and SW perimeter.



Photo#3:



Photo#4:
Dense stands of thistle show down grade of SW Corner.

September 23, 2020



Photo#5:

GE 2014 aerial of Location. Red circle indicates weed area of concern.

September 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Foundation Energy PA Arkansas Post API#081-07357