

Inspection Photos
Operator: BP America
API: 067-08701
Date: 11/17/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with grasses such as smooth brome, crested wheatgrass, and sand dropseed.



Photo 3. View of Russian knapweeds within the northwestern project area. Approximately 1000 individuals observed.



Photo 4. View of the reference area comprised of sagebrush shrubland with scattered pinyon and juniper trees and understory of grasses and forbs such as western wheatgrass and snakeweed.