

Inspection Photos
Location Name: Federal 1-33-7
Location ID: 313061



Photo 1. Overview of location taken facing southwest.

Inspection Photos
Location Name: Federal 1-33-7
Location ID: 313061



Photo 2. No bradenhead access apparent.



Photo 3. Ice from high pressure leak at separator.