

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 1 – Tank Battery



Photo 2 – Heater Treater



Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 3 – Tank Battery Sign



Photo 4 – Wellhead

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 5 – Flare and ECD



Photo 6 – Tank Battery



Inspection Photos
Location Name: Logan 2H
Location ID: 430811




Photo 7 – Stained Soil at Gas Engine



Photo 8 – Stained Soil North of Gas Engine Shed

