

BP L48 San Juan



## V2 Compliance Follow Up Form

18162775533

**Reference Number:**

**Form Name:**

**Submitter Name:**

**Submission Date:**

**Location:**

20201117-18162775533

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Nov 17, 2020 2:43:03 PM MST

557 Airpark Dr, Durango, CO 81303, USA

Nov 17, 2020 2:46:52 PM MST [ [View Map](#) ]

## INFORMATION

### Section 1

**Name**

colen@horizonenvservices.com

**Date**

Nov 17, 2020

**Well Name**

KENNEDY GAS UNIT A 1

**API Number**

50670701000

**Select State**

Colorado

**Work type**

BP call out

**Action Complete**

Clean Up Weed Debris

**Photo of first corrective action completed**



Completed work description Corrective  
Action 1

location sign

Photo of second corrective action completed





**Completed work description of corrective action 2**

removed weed debris from reclamation area

**Photo of third corrective action completed**





**Completed work description of corrective action 3**

removed weed debris from reclamation area

**Photo of fourth corrective action completed**



**Completed work description**

removed weed debris

**Completed work description of corrective action 4**

removed weed debris from reclamation area

**Additional photos**





**Completed work description**

removed weed debris

**Summary of all work completed**

previous treatment dates 7/9/17, 7/6/18, 6/6/19,  
6/30/20