

Inspection Photos
Location Name: McCallum 157
Location ID: 324726



**Photo 1. Overview of location taken facing northwest.
Unused open top tank with no secondary containment.**



Photo 2. No bradenhead access apparent.

