

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NENE

Location ID: 334569



Photo #2699 from entrance to location.



Photo #2700 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NENE

Location ID: 334569



Photo #2701 Multiple wellhead signs weathered and not legible.



Photo #2702 Multiple wellhead signs weathered and not legible.