


Inspection Photos
Location Name: Nelson Ranches 1-27-10-59 PAD
Location ID: 433228



Colorado Oil and Gas Conservation Commission
40.81019, -103.97571, 5086.8ft, 172°
02/17/2021 13:52:08

Photo 1 – Pumping Units and Wellheads



Colorado Oil and Gas Conservation Commission
40.81037, -103.97616, 5088.1ft, 248°
02/17/2021 13:34:58

Photo 2 – Tank Battery Sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Nelson Ranches 1-27-10-59 PAD
Location ID: 433228



Photo 3 – Tank Battery



Photo 4 – SE Water Tank missing NFPA label



Inspection Photos
Location Name: Nelson Ranches 1-27-10-59 PAD
Location ID: 433228



Photo 5 – Riser has been marked



Photo 6 – Compressor