

Inspection Photos

Location Name: CAERUS PICEANCE LLC Cook Martin /20-1D (PB-20)

Location ID: 422328



Photo #3058 from entrance to location.

Photo #3059 from entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Cook Martin /20-1D (PB-20)

Location ID: 422328



Photo #3061 Flow line heating insulation open ended and not capped.



Photo #3062 debris on location.