

**Inspection Photos**  
**Location Name: Tigges 3-31B**  
**Location ID: 327053**



**Photo 1: Wrong wellhead name displayed**



**Photo 2: Pumpjack**



**Inspection Photos**  
**Location Name: Tigges 3-31B**  
**Location ID: 327053**



**Photo 3: Stained soil**



**Photo 4: Stained soil**





**Inspection Photos**  
**Location Name: Tigges 3-31B**  
**Location ID: 327053**



**Photo 5: Unused equipment, weeds**



**Photo 6: Unused equipment**



**Inspection Photos**  
**Location Name: Tigges 3-31B**  
**Location ID: 327053**



**Photo 7: Unused equipment**



**Photo 8: Unused equipment**

**Inspection Photos**  
**Location Name: Tigges 3-31B**  
**Location ID: 327053**



**Photo 9: Weeds**



**Photo 10: Unable to read tank battery sign**





**Inspection Photos**  
**Location Name: Tigges 3-31B**  
**Location ID: 327053**



**Photo 11: No contents/capacity/NFPA placard on tank**



**Photo 12: Inadequate berm**



**Inspection Photos**  
**Location Name: Tigges 3-31B**  
**Location ID: 327053**



**Photo 13: Inadequate berm**



**Photo 14: Inadequate berm**

