

# *Inspection Photos*

*Loc#335777*

*Operator: Terra*

*Insp#: 692403184*

*Insp Date: 3/5/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
View over Location from entry.

March 5, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Insp Photos:Terra Federal Loc#335777





Photo#2:  
Rutting on site.

March 5, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#3:  
BMPs being undercut or by-passed by  
stormwater.

Insp Photos:Terra Federal Loc#335777