

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #3143 from entrance to location.



Photo #3144 Trash by tank battery.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #3145 Location lacks stabilization.



Photo #3146 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #3147 No form of tracking at entrance to location.