

Inspection Photos

Loc#334575

Operator: Caerus

Insp#: 692403239

Insp Date: 3/17/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location. Insert, rutting, unstable working surface.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Rose Ranch Loc#334575



Photo#2:
Interim area.



Photo#3:
Interim area.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Rose Ranch Loc#334575