

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2021

Submitted Date:

03/29/2021

Document Number:

700702481

FIELD INSPECTION FORM

Loc ID 335307	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 14 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260285	WELL	PR	11/08/2013	GW	045-07841	COUEY 31-8 (B31)	PR
260286	WELL	PR	07/29/2002	GW	045-07842	COUEY 31-7 (B31)	PR
260287	WELL	PR	12/06/2002	GW	045-07843	COUEY 31-2 (B-31)	PR
260288	WELL	PR	08/06/2002	GW	045-07844	SHAEFFER 31-3 (B31)	PR
262207	WELL	PR	05/10/2012	GW	045-08003	COUEY 31-7B2 (B31)	PR
262208	WELL	PR	07/23/2002	GW	045-08004	COUEY 31-1C2 (B-31)	PR
262968	WELL	PR	08/09/2002	GW	045-08077	COUEY 30-15 (B31)	PR

General Comment:

COGCC Inspection Report Summary
 On Wednesday 3/24/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus B31, at Location # 335307 in Garfield county Colorado.
 While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.
 During this inspection the following possible compliance issues were observed:
 1. Tank battery signage does not meet requirements of new rule 605.e
 Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	1. Tank battery signage does not meet requirements of new rule 605.e		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	05/25/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	500 gallon methanol tank in tank battery containment		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:	Two (2) tanks are in a seperate containment				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	260285	Type:	WELL	API Number:	045-07841	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	260286	Type:	WELL	API Number:	045-07842	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	260287	Type:	WELL	API Number:	045-07843	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	260288	Type:	WELL	API Number:	045-07844	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	262207	Type:	WELL	API Number:	045-08003	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	262208	Type:	WELL	API Number:	045-08004	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	262968	Type:	WELL	API Number:	045-08077	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Berms						
Gravel						
		Ditches				
Ditches						
		Culverts				
		Gravel				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702487	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5387859