

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Laramie Land & Cattle Co /36-10 Pad

Location ID: 334516



Photo #3329 from entrance to location.



Photo #3330 from entrance to location

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Laramie Land & Cattle Co /36-10 Pad

Location ID: 334516



**Photo #3331 Location lacks stabilization.**



**Photo #2338 From inspection #699802170 conducted on 11/30/20.**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Laramie Land & Cattle Co /36-10 Pad

Location ID: 334516



Photo #3332 Location lacks stabilization.



Photo #2339 From inspection #699802170 conducted on 11/30/20.

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Laramie Land & Cattle Co /36-10 Pad

Location ID: 334516



**Photo #3333 No form of tracking control at entrance to location**



**Photo #2340 From inspection #699802170 conducted on 11/30/20.**


## Inspection Photos

Location Name: LARAMIE ENERGY LLC Laramie Land & Cattle Co /36-10 Pad

Location ID: 334516



**Photo #3334 No form of tracking control at entrance to location.**



**Photo #2341 From inspection #699802170 conducted on 11/30/20.**