

Inspection Photos

API: 071-08321

Operator: OGRIS OPERATING LLC

Inspection Date: 4/1/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 4/1/2021

Inspection Photos



Photo 1. Facing toward the access road. The access road is rutted and not stabilized and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 4/1/2021

Inspection Photos



Photo 2. Facing back down toward the access road. The access road is rutted and not stabilized and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 4/1/2021

Inspection Photos



Photo 3. Facing toward the location.



Inspection Photos



Photo 4. There is oil stained soil and oil in the engine skid which needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 4/1/2021