

Inspection Photos
Location Name: Duncan Van Schaick 1-5
Location ID: 313207



Photo 1. Overview of location taken facing north. Dried annual weeds on location.



Photo 2. No bradenhead access apparent. Dried annual weeds on location.

