

Inspection Photos
Location Name: McCallum 169
Location ID: 324731



Photo 1. Overview of location taken facing south.



Inspection Photos
Location Name: McCallum 169
Location ID: 324731



Photo 2. Stained soil on location.



Photo 3. No bradenhead access apparent.