

Inspection Photos
Location Name: Cleveland #3
Location ID: 318056



Photo 1 WH sign

Photo 2 WH/sign

Inspection Photos
Location Name: Cleveland #3
Location ID: 318056



Photo 3 Unused equipment no meters on meter boxes

Photo 4 electric panel is shut off

Inspection Photos
Location Name: Cleveland #3
Location ID: 318056




Photo 5 Unused equip. pump jack is not attached to well

Photo 6 Unused equip. No motor on pump jack