

Inspection Photos
Location Name: Behring 23-7 Tank Battery
Location ID: 332096



Photo 1 – Tank Battery Sign



Photo 2 – Tank Battery

Inspection Photos
Location Name: Behring 23-7 Tank Batttery
Location ID: 332096



Photo 3 – Heater Treater



Photo 4 – Compressor

Inspection Photos
Location Name: Behring 23-7 Tank Batttery
Location ID: 332096



Photo 5 – West Tank Loadline



Photo 6 – Unmarked Riser at Heater

Inspection Photos
Location Name: Behring 23-7 Tank Batttery
Location ID: 332096




Photo 7 – Unmarked Risers at Tanks




Photo 8 – Unmarked Risers at the back of Tanks

Inspection Photos
Location Name: Behring 23-7 Tank Batttery
Location ID: 332096



Photo 9 – Unmarked Risers at the back of the West Tank



Photo 10 – Pit

Inspection Photos
Location Name: Behring 23-7 Tank Batttery
Location ID: 332096



Photo 11 – Hole in Netting



Photo 12 – Netting at Pit NOT Secure. Wildlife Hazard

Inspection Photos
Location Name: Behring 23-7 Tank Batttery
Location ID: 332096



Photo 13 – Netting at Pit NOT Secure. Wildlife Hazard