

# Interim Reclamation and Stormwater Inspection

May 20, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 453934

Inspection Document #: 697502941

Adams County, CO

SESE Section 30 T1S R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Edmundson /30  
Location ID: 453934



**Photo 1.** Photo taken from the northern location, facing East. Photo illustrates a cut slope that has been seeded and hydromulched.



**Photo 2.** Photo taken from a section of the northern location. Photo illustrates a List B Colorado noxious weed, Scotch thistle.





Inspection Photos  
Location Name: Edmundson /30  
Location ID: 453934



**Photo 3.** Photo taken from the northwestern location, facing South. Photo illustrates a stormwater BMP and the topsoil stockpile.



**Photo 4.** Photo taken from the western location, facing Southeast. Photo illustrates the topsoil stockpile has been tracked, seeded and hydromulched. Germination of desirable plant species were observed throughout most of the stockpile. There was a bare area along the southern stockpile.





Inspection Photos  
Location Name: Edmundson /30  
Location ID: 453934



**Photo 5.** Photo taken from the southwestern location. Photo illustrates a List B Colorado noxious weed, Canada thistle.



**Photo 6.** Photo taken from the southeastern location, facing Northeast. Photo illustrates a sediment trap with a temporarily stabilized outlet.

