

Inspection Photos
Location Name: Timbro LD 06-64HN
Location ID: 433177



Photo 1 – Wellhead

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Timbro LD 06-64HN
Location ID: 433177



Colorado Oil and Gas Conservation Commission
40.7774, -103.91718, 4800.5ft, 72°
06/02/2021 13:06:22



Colorado Oil and Gas Conservation Commission
40.77726, -103.91701, 4814.1ft, 280°
06/02/2021 13:06:39

Photo 3 – Gas Meters and Compressor

Photo 4 – Separators and ECDs

Inspection Photos
Location Name: Timbro LD 06-64HN
Location ID: 433177



Photo 5 – VRUs

Photo 6 – Tank Battery

Inspection Photos
Location Name: Timbro LD 06-64HN
Location ID: 433177



Photo 7 – Tank Battery Sign

Photo 8 – Capacity Label Missing

Inspection Photos
Location Name: Timbro Federal LD 07-78HN
Location ID: 432189



Colorado Oil and Gas Conservation Commission
40.77753, -103.91705, 4819.6ft, 143°
06/02/2021 13:14:49



Colorado Oil and Gas Conservation Commission
40.7775, -103.91711, 4826.6ft, 204°
06/02/2021 13:15:38

Photo 9 – Compressor

Photo 10 – Day Tank Netting inadequate

Inspection Photos
Location Name: Timbro Federal LD 07-78HN
Location ID: 432189



Photo 11 – Stained Soil at Compressor