

Inspection Photos

6/08/2021

Operator: LARAMIE ENERGY LLC # 10433

Location ID: 334537

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: LARAMIE ENERGY LLC # 10433

Location ID: 334537



Photo 1: Photo taken from the northwestern end of the Location, facing east. Photo shows interim reclamation activities were in process at time of inspection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334537



Photo 2: Photo shows liner/trash observed on the north end of the Location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334537



Photo 3: Photo shows noxious weeds (Bindweed, white flowers) observed on the production areas.



Inspection Photos

Operator Name: LARAMIE ENERGY LLC # 10433

Location ID: 334537



Photo 4: Photo shows noxious weeds (Bindweed, white flowers) observed on the western remediation areas.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334537



Photo 5: Photo shows noxious weeds (Bindweed, white flowers) observed on the fill slopes.



Inspection Photos

Operator Name: LARAMIE ENERGY LLC # 10433

Location ID: 334537



Photo 6: Photo shows noxious weeds (Bindweed, white flowers) observed on the access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources