

Inspection Photos

Location Name: SG INTERESTS I LTD FALCON SEABOARD-611S90W /12SWNW

Location ID: 311729



Photo #3970 from entrance to location.



Photo #3971 from entrance to location.

Inspection Photos

Location Name: SG INTERESTS I LTD FALCON SEABOARD-611S90W /12SWNW

Location ID: 311729



Photo #3972 location lacks stabilization.



Photo #3973 location lacks stabilization.

Inspection Photos

Location Name: SG INTERESTS I LTD FALCON SEABOARD-611S90W /12SWNW

Location ID: 311729



Photo #3974 No form of tracking BMP located at the entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources