

Inspection Photos

API#107-06123

Operator: Bayless

Insp#: 692403498

Insp Date: 6/9/2021





Photo#1:

View of Location from entry to Northwest. Note Houndstongue plants in foreground.

June 9, 2021



Photo#2:

Steep access road into Location, view to Northwest. Note Houndstongue and white top along and on roadway.

June 9, 2021



Photo#3:
Weed establishment, lack of desirable vegetation.



Photo#4:
Weed establishment, lack of desirable vegetation

June 9, 2021



Photo#5:
Erosion on West side of site.



Photo#6:
Erosion on West side of site

June 9, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Robert L Bayless PA Grassy Creek Coal API#107-06123