

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /20SESW

Location ID: 335183



Photo #4172 from entrance to location.

Photo #4173 No battery sign located at the tank battery.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /20SESW

Location ID: 335183

Network: Jun 24, 2021 at 1:52:28 PM MD
Local: Jun 24, 2021 at 1:52:28 PM MD



Photo #4174 wellhead sign weathered and not legible.