

Inspection Photos

Location Name: LARAMIE ENERGY LLC Pond 13 Central E&P Facility /13W & 13E

Location ID: 335849



Photo #4668 from entrance to location.



Photo #4669 No battery sign located at the tank battery.



Inspection Photos

Location Name: LARAMIE ENERGY LLC Pond 13 Central E&P Facility /13W & 13E

Location ID: 335849



Photo #4670 Location lacks stabilization.



Photo #4671 Location lacks stabilization.



Inspection Photos

Location Name: LARAMIE ENERGY LLC Pond 13 Central E&P Facility /13W & 13E

Location ID: 335849



Photo #4672 No form of tracking BMP located at entrance to location.