

Caerus Piceance LLC
Figure Four M11
Location # 335785



location



location

Caerus Piceance LLC
Figure Four M11
Location # 335785



Location/lack of battery signage



Location/lack of battery signage



Caerus Piceance LLC
Figure Four M11
Location # 335785



location



Lack of stabilization/compaction



Caerus Piceance LLC
Figure Four M11
Location # 335785



Entrance/access erosion



Outlet of culvert



Caerus Piceance LLC
Figure Four M11
Location # 335785



Exposed culvert in center of entrance



Culvert inlet?

