

Caerus Piceance LLC
Figure Four B15
Location # 335791



Location/lack of battery signage



location



Caerus Piceance LLC
Figure Four B15
Location # 335791



location



Open holes on glycol baths

Caerus Piceance LLC
Figure Four B15
Location # 335791



Open holes on glycol baths



Plastic caps on heaters



**Caerus Piceance LLC
Figure Four B15
Location # 335791**



**Access road erosion/lack of
stabilization/compaction**



**Access road erosion/lack of
stabilization/compaction**