

# Inspection Photos

8/13/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 312431


Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location ID: 312431



**Photo 1:** COGIS imagery showing two Locations (Vega Pad #4, Vega Unit-69S93W 35NESW) were permit adjacent to each other, with the Vega 4 Well located just south of the active site.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location ID: 312431



**Photo 2:** Google Earth aerial image showing location of the Vega Unit 4 well (API 05-077-08189) actual location as indicated by Form 6(s) #401337066. Well was PA on the Vega Unit 4 Location, and not to the south as indicated by the well files.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location ID: 312431



**Photo 3:** Photo shows all wells on the Location. Star indicates approximate Location of the Vega Unit 4 well (API 05-077-08189) as indicated by Form 6(s) #401337066.