

Inspection Photos

9/24/2021

Operator: GUNNISON ENERGY LLC # 10515

Location ID: 324459

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324459



Photo 1: Photo taken from the production areas on the Location. Photos show control measures to stabilize/protect the production area are missing or insufficient; vehicle rutting, tracking and degradation observed on pad and location entrance.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324459



Photo 2: Photo taken from the production areas on of the Location. Photos shows control measures to stabilize/protect the production area are missing or insufficient; vehicle rutting, tracking and degradation observed on pad and location entrance.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324459



Photo 3: Photos taken from the west end of the Location. Photo shows vehicle travel and storage of trailers on the interim and off-site areas of the Location has resulted in additional degradation and disturbance. Areas require reclamation.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324459



Photo 4: Photos taken from the southern end of the Location. Photo shows vehicle travel and storage of trailers on the interim and off-site areas of the Location has resulted in additional degradation and disturbance. Areas require reclamation.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC # 10515

Location ID: 324459



Photo 5: Photos taken from the access road on the north end of the Location. Photo shows vehicle travel on off-site areas of the Location has resulted in additional degradation and disturbance. Areas require reclamation.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324459



Photo 6: Photo shows trailers stored on interim/off-site areas of the Location, and the eastern areas of the pad.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324459



September 24, 2021
39.14231449N 107.45914347W

Photo 7: Photo shows stained soils observed to the southwest of the well.