

Inspection Photos
Location Name: Speaker 27-8-61
Location ID: 434772



Photo 1 – Pumping Units

Photo 2 – Flare

Inspection Photos
Location Name: Speaker 27-8-61
Location ID: 434772



Photo 3 – Heater Treater and ECDs



Photo 4 – Tank Battery

Inspection Photos
Location Name: Speaker 27-8-61
Location ID: 434772



Photo 5 – Tank Battery Sign

Photo 6 – West Heater Treaters

Inspection Photos
Location Name: Speaker 27-8-61
Location ID: 434772



Photo 7 – Calibration Card is Missing