

Caerus Piceance LLC
PCU T62X-11G
Location # 335711



Location



location

Caerus Piceance LLC
PCU T62X-11G
Location # 335711



Oct 18, 2021 at 11:13:13 AM
+39.896951,-108.245230 ±4.68m
COGCC

Location



Oct 18, 2021 at 11:16:05 AM
+39.896943,-108.245485 ±4.79m
COGCC

location

Caerus Piceance LLC
PCU T62X-11G
Location # 335711



Location



location/lack of battery signage

Caerus Piceance LLC
PCU T62X-11G
Location # 335711



Location



Debris

Caerus Piceance LLC
PCU T62X-11G
Location # 335711



Fill slope erosion



Fill slope erosion/sediment migration

Caerus Piceance LLC
PCU T62X-11G
Location # 335711



Fill slope erosion



Fill slope erosion

Caerus Piceance LLC
PCU T62X-11G
Location # 335711



Lack of stabilization