

# Inspection Photos

API: 087-07201

Operator: PETRON DEVELOPMENT COMPANY

Inspection Date: 10/25/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 087-07201 | Date: 10/25/2021

## Inspection Photos



**Photo 1.** Drone aerial photo facing northwest toward the well site location. There is a livestock water tank located at the yellow arrow.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 087-07201 | Date: 10/25/2021

## Inspection Photos



**Photo 2.** Drone aerial photo facing east toward the well site location. The associated pit is located at red arrow. There is a livestock water tank located at yellow arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 087-07201 | Date: 10/25/2021

## Inspection Photos



**Photo 3.** Facing east. The JAMES HUNT 1 Pit is not closed and reclaimed per 1004 Rules.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 087-07201 | Date: 10/25/2021

## Inspection Photos



**Photo 4.** Facing southeast. It appears there was a former spill that occurred downhill from the pit shown in the direction of the red arrow. This area has insufficient vegetation re-establishment and extends out approximately 450' from the pit.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 087-07201 | Date: 10/25/2021

## Inspection Photos



**Photo 5.** Facing southeast toward the pit. There is exposed piping shown at red arrow. The piping equipment was never removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 087-07201 | Date: 10/25/2021