

Inspection Photos

API: 099-06059

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 11/30/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06059 | Date: 11/30/2021

Inspection Photos



Photo 1. There is abandoned pipe riser that remains at the location which needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06059 | Date: 11/30/2021